บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

# Inspection Report (ตรวจสภาพเครื่องจักร)

## Product detail : FORKLIFT Maker DOOSAN Model D30G Serial FDA0D-1670-09885

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

| Category | Type | Maker | Model |
|---|---|---|---|
| FORKLIFT | FORKLIFT | DOOSAN | D30G |
| **Serial** | **Engine** | **Chassis** | **Year** |
| FDA0D-1670-09885 | 4TNE98-BQDFC B2828 | | |

| Check Point | |
|---|---|
| **Operator** | Canopy |
| **Monitor Panel** | Repair — ขึ้นไม่ครบ |
| **Hour Meter Activity** | Repair — ไม่ขึ้น |
| **Air Condition** | Non |
| **Engine Operation** | |
| **Number of Cylinder** | 4 Cylinder — 4TNE98 |
| **Fuel Type** | Diesel |
| **Engine Noise** | Normal |
| **Black - White Smoke** | Fair — ควันเริ่มขาว |
| **Type Transmission** | Auto |
| **Gear Working Condition** | Normal |
| **Water Leak from Water Pump** | Normal |
| **Water Leak from Radiator** | Normal |
| **Remark** | |
| **Details** | |
| **Hydraulic System** | |
| **Oil leak from Valve,Hose** | Normal |
| **Hyd.Pump Condition** | Normal |
| **Hydraulic Oil** | Normal |
| **Hydraulic Cylinder Working Condition** | |
| **Lift fork Cylinder Working Condition** | Normal |
| **Tilt Mast Cylinder Working Condition** | Normal |
| **General Working Condition** | |
| **SIze of Mast** | |
| **The Height of Mast** | Centimeter — 300 ซม.□ |
| **Special features of Mast** | |
| **Special features of Fork** | |
| **The Length of Fork** | Centimeter — 150 ซม.□ |
| **Characteristics of Rubber** | |
| **Battery Condition** | Dead — ต้องพ่วง |