บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Maker YANMAR Model CT340 Serial F34A-10051

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	YANMAR	CT340
Serial	**Engine**	**Chassis**	**Year**
F34A-10051	3TNV88 02 00495		

Check point	
Operator	Hood
Monitor Panel	Normal – แสดงผลครบ
Hour Meter Activity	Normal – 3035
Air Condition	NONE
Engine Operation	
Number of Pistons	3 Pistons
Fuel Type	Diesel
Engine Noise	Fair
Black-White Smoke	Fair
Type Transmition	Auto
Water Leak form Water Pump	Fair
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condiction	Normal
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 2 – ล้อแทรคยาง
Special Accessories	NONE
Gear Working Condiction	Normal
Gear Working Condition PTO	Normal
Battery	Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	More