บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : HYD. EXCAVATOR Year 2011 Maker SUMITOMO Model SH75X-3B Serial *SMT075X3E00BB7884*

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

Category	Type	Maker	Model
EXCAVATOR	HYD. EXCAVATOR	SUMITOMO	SH75X-3B
Serial	**Engine**	**Chassis**	**Year**
SMT075X3E00BB7884	4LE2 268468		2011

Check Point	
Operator	Cabin
Monitor Panel Condition	Normal — แสดงผลครบ
Hour Meter Activity	Normal — 0096
Air Condition	Normal
Remark	
Details	
Engine Condition	
Number of Cylinder (Cylinder)	4 Cylinder
Engine Noise	Fair
Black - White Smoke	Fair
Water Leak from Water Pump	Fair
Water Leak from Radiator	Normal
Hydraulic System	
Oil leak from Valve	Fair
Hyd.Pump Working Condition	Normal — ใช้งานได้ปกติ
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Fair
Bucket Cylinder Working Condition	Fair
Arm Cylinder Working Condition	Fair
Blade Cylinder Working Condition	Fair — ไม่รั่ว ไม่ซึม
General Working Condition	
Swivel Bearing & Swivel Motor Condition	Normal
The overall condition of the undercarriage	Fair
Shoe Size (Centimeter)	Centimeter — แทรคเหล็ก 45
Battery Condition	Have — สตาร์ทได้เลย ใช้งานได้ตามปกติ