บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Year 1985 Maker HONDA Model MIGHTY-11 Serial 1001013

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	HONDA	MIGHTY-11
Serial	**Engine**	**Chassis**	**Year**
1001013	GC05-1024437		1985

Check point	
Operator	NONE – เบาะสภาพดี
Monitor Panel	Normal – แสดงผลครบ
Hour Meter Activity	Normal – ไม่มี
Air Condition	NONE
Engine Operation	
Number of Pistons	Other – 1สูบ เครื่องแห้ง ไม่เย็น
Fuel Type	Benzin
Engine Noise	Normal
Black-White Smoke	Normal
Type Transmition	Manual
Water Leak form Water Pump	Fair
Water Leak form Radiater	Fair
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condiction	Normal – ใช้งานได้
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 4
Special Accessories	Rotary – หมุนได้,ขึ้นลงได้
Gear Working Condiction	Normal
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ
Battery	No Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	