บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

# Inspection Report (ตรวจสภาพเครื่องจักร)

## Product detail : BATTERY FORKLIFT Year 1998 Maker TOYOTA Model 5FBE10 Serial 5FBE13-11329

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 3% THAI IMPORT DUTY / มีค่าอากรนำเข้า 3%

| Category | Type | Maker | Model |
|---|---|---|---|
| FORKLIFT | BATTERY FORKLIFT | TOYOTA | 5FBE10 |
| **Serial** | **Engine** | **Chassis** | **Year** |
| 5FBE13-11329 | | | 1998 |

| Check point | |
|---|---|
| **Operator** | Sit and drive – เบาะ สภาพดี ไม่ขาด |
| **Monitor Panel** | Normal – แสดงผลครบ |
| **Hour Meter Activity** | Normal – 25931 |
| **Battery** | |
| **Battery size** | 48 V. |
| **Battery Condition** | NONE – มีเสื่อมสภาพตามการใช้งาน |
| **Moter Operatiot** | |
| **Driving Moter** | Normal |
| **Truning Moter** | Normal |
| **Hydraulic System** | |
| **Oil leak from Valve,Hose** | Normal |
| **HYD. Pump Condition** | Normal – ใช้งานได้ |
| **Hydraulic Oil** | Normal |
| **Hydraulic Cylinder Working Condition** | |
| **Lift fork Cylinder** | Normal – ใช้งานได้ตามปกติ |
| **Lifting Cylinder** | Normal – ใช้งานได้ตามปกติ |
| **Extension Fork Cylinder** | Normal – ไม่มี |
| **General Working Condition** | |
| **SIze of Mast** | 2 Pieces |
| **Height of Mast** | Cantimeter – 300 |
| **Special features of Mast** | Normal |
| **Special features of Fork** | Slide Shift |
| **Length of Fork** | Cantimeter – 110 |
| **Wheel Characteristics** | Normal |
| **Remark** | |
| **Details** | |