บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : HYD. EXCAVATOR Year 2012 Maker CATERPILLAR Model 312D Serial *CAT0312DAFBJ02172*

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

Category	Type	Maker	Model
EXCAVATOR	HYD. EXCAVATOR	CATERPILLAR	312D
Serial	**Engine**	**Chassis**	**Year**
CAT0312DAFBJ02172	C4.2 JKH16877		2012

Check Point	
Operator	Cabin
Monitor Panel Condition	Normal — ขึ้นครบ
Hour Meter Activity	Normal — 7978
Air Condition	Fair
Remark	
Details	
Engine Condition	
Number of Cylinder (Cylinder)	4 Cylinder — C4.2
Engine Noise	Normal
Black - White Smoke	Normal
Water Leak from Water Pump	Normal
Water Leak from Radiator	Normal
Hydraulic System	
Oil leak from Valve	Normal
Hyd.Pump Working Condition	Normal
Hydraulic Oil	Normal
Hydraulic Cylinder Working Condition	
Boom Cylinder Working Condition	Normal
Bucket Cylinder Working Condition	Normal
Arm Cylinder Working Condition	Normal
Blade Cylinder Working Condition	Normal — ไม่มีใบมีด
General Working Condition	
Swivel Bearing & Swivel Motor Condition	Normal
The overall condition of the undercarriage	Normal
Shoe Size (Centimeter)	Centimeter — 70 ซม.□
Battery Condition	Dead — ต้องพ่วง