บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Year 1972 Maker MITSUBISHI Model D1100 Serial M72-10460

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	MITSUBISHI	D1100
Serial	**Engine**	**Chassis**	**Year**
M72-10460	KE55 13212		1972

Check point	
Operator	NONE
Monitor Panel	Normal
Hour Meter Activity	NONE
Air Condition	NONE
Engine Operation	
Number of Pistons	2 Pistons – KE55
Fuel Type	Diesel
Engine Noise	Normal
Black-White Smoke	Normal
Type Transmition	Manual
Water Leak form Water Pump	Normal
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condiction	Normal
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 2
Special Accessories	NONE
Gear Working Condiction	Normal
Gear Working Condition PTO	Normal
Battery	No Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	