



บริษัท สหเศรษฐ์ อ็อกชั่น จำกัด  
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสอบสภาพเครื่องจักร)

Product detail : MANLIFT Maker AIRMAN Model ENTLO61 Serial ENTLO62207

\*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ

\*This report is only for your reference. We are not responsible for the actual condition of checked item

\*\*\* EXCLUDE 5% THAI IMPORT DUTY / มีค่าอากรนำเข้า 5%

| Category   | Type    | Maker   | Model   |
|------------|---------|---------|---------|
| MANLIFT    | MANLIFT | AIRMAN  | ENTLO61 |
| Serial     | Engine  | Chassis | Year    |
| ENTLO62207 |         |         |         |

| Check point                    |                                               |
|--------------------------------|-----------------------------------------------|
| Operator                       | Scissor Lift                                  |
| Propulsion                     | Battery                                       |
| Basket Size                    | Width×Length – 70×170                         |
| Battery size                   | 24 Volt                                       |
| Engine Size                    | NONE                                          |
| Hour Meter Activity            | Hour – 0468                                   |
| General Working Condition      |                                               |
| Engine Operation               | NONE                                          |
| Working of Hydraulic Pump      |                                               |
| Operation of The Working Motor |                                               |
| Basket height                  | Cantimeter – 600                              |
| Number of batteries            | 4 unit                                        |
| Hydraulic System               |                                               |
| Oil leak from Valve,Hose       |                                               |
| HYD. Pump Condition            |                                               |
| Hydraulic Oil                  |                                               |
| Remark                         |                                               |
| Details                        | More – ระบบไม่ทำงาน บางรายการไม่สามารถเช็คได้ |