บริษัท สหเครน อ๊อกชั่น จำกัด
SAHA CRANE AUCTION CO.,LTD.

Inspection Report (ตรวจสภาพเครื่องจักร)

Product detail : AGRICULTURAL TRACTOR Year 1989 Maker YANMAR Model UP-2 Serial 010481

*รายงานฉบับนี้จัดทำขึ้นเพื่อการอ้างอิงเท่านั้น บริษัทฯ ไม่รับรองหรือรับผิดชอบต่อสภาพจริงของรายการที่ได้รับการตรวจสอบ
*This report is only for your reference. We are not responsible for the actual condition of checked item

*** EXCLUDE 20% THAI IMPORT DUTY / มีค่าอากรนำเข้า 20%

Category	Type	Maker	Model
AGRICULTURAL TRACTOR	AGRICULTURAL TRACTOR	YANMAR	UP-2
Serial	**Engine**	**Chassis**	**Year**
010481	GA340SEKS 08879		1989

Check point	
Operator	NONE – เบาะสภาพดี
Monitor Panel	NONE
Hour Meter Activity	NONE
Air Condition	NONE
Engine Operation	
Number of Pistons	Other – 1สูบ เครื่องแห้ง ไม่เย็น
Fuel Type	Benzin
Engine Noise	Fair
Black-White Smoke	Normal
Type Transmition	Manual
Water Leak form Water Pump	Normal
Water Leak form Radiater	Normal
Hydraulic System	
Oil Leak form Velve,Hose	Normal
HYD. Pump Condiction	Normal – ใช้งานได้
Hydraulic Oil	Normal
General Working Condition	
Drive Shaft Size	Drive 4
Special Accessories	Rotary – คานยกโรตารี่ใช้งานไม่ได้
Gear Working Condiction	Normal
Gear Working Condition PTO	Normal – ใช้งานได้ปกติ
Battery	No Have
Battery Condition	No Good – ต้องพ่วง
Remark	
Details	